

57460 Dewitt Street = Elkhart, Indiana 46517-1078 Phone (574) 293-9096 = Fax (574) 294-3450 800-628-2957 = Web site: www.rpiroyaledge.com



RPI ROYAL EDGE SPLICE ADHESIVE (CLEAR) TECHNICAL DATA SHEET

PRODUCT DATA	
SOLIDS: 26% Minimum	BASE: Synthetic Polymers
COLOR: Clear	SOLVENTS: Hexane, Toluene, Xylene
WEIGHT:	BASE:
7.35 ± .37 lb/gal	Rubber Polymers
FLASH POINT: 0° F (-17.8° C)	SPECIFIC GRAVITY: .0876 ± 5%
CONTENT: 5.13 lb/gal	VISCOCITY: 2900-3700 Centipoises, R.V.F. #3



DESCRIPTION:

RPI Splice Adhesive is formulated to splice Royal Edge membrane flashing, Royal Edge Uncured Flashing, field membrane panels, metal flashing surfaces, and other details specified in the RPI Specification Manual.

APPLICATION INSTRUCTIONS:

- 1. Position the membrane to overlap the required distance for the entire length of the seam area. All seams should be 6 inches minimum. Fold the top ply back to allow for cleaning both surfaces (top and bottom ply) that are to be spliced. Remove any loose dust and debris. Wearing protective gloves, clean the seam area using clean cotton cloths that are saturated with RPI Membrane Cleaner.
- 2. Clean thoroughly to remove all talc and debris from area to be seamed. Change cotton rags often to prevent overloading of rags. Cleaned area should be dark grey in color with no streaking.
- 3. Thoroughly stir RPI Splice Adhesive before, and during use. Splice Adhesive should be uniformly mixed without marbling.
- 4. Apply Splice Adhesive using a stiff solvent resistant paint brush using even back and forth brush strokes. Do not apply using circular motions.
- 5. Both surfaces should be coated at the same time, using a uniform (no puddles) amount of Splice Adhesive throughout the splice area. Allow splice area to flash-off.
- 6. Prior to mating the splice surfaces, test the adhesive using the finger push method. Flash-off time is dependent upon ambient air temperatures and air/moisture content.
- 7. When both surfaces have flashed-off, allow the top splice layer to roll onto the bottom layer and mate the surfaces together by sliding a hand over the splice area from the back of the seam towards the front leading edge. The splice area membrane should be allowed to lay comfortably into position. Do not stretch or allow wrinkles to form in the seam area.
- 8. Using a 2 inch steel, or silicone hand roller, apply pressure to the seam area by first rolling across the seam area, then rolling the length of the seam area.
- 9. Clean the seam edge with Membrane Cleaner and apply Lap Caulk according to RPI Specifications.

COVERAGE RATES:

All field seams created using RPI Splice Adhesive should be a minimum of 6 inches wide. 120 linear ft. of finished seam per gallon is expected.

PACKAGEING:

<u>Available in:</u> 1 gallon pails 5 gallon pails

4-pails per carton 45 pails per pallet

PRECAUTION DATA:

- 1. **Flammable.** Do not smoke when using. Keep away from open flames, sparks, and other sources of ignition.
- 2. Avoid contact with skin and eyes. Protective eyewear along with OSHA approved gloves should be worn.
- 3. Do not thin.
- 4. When using in cold temperatures, keep adhesive at room temperature when applying.
- 5. RPI Membrane Cleaner is recommended for clean-up.
- 6. Always cover adhesive when not is use. Do not allow adhesive to "skin over", or sit open for extended periods. Opened containers can be sealed and reopened depending upon storage conditions and previous open time. Reuse after one week is not recommended.
- 7. For professional use only.
- 8. Use only in well ventilated areas.
- 9. Refer the RPI Specifications and MSDS data prior to application of Splice Adhesive.

SHELF LIFE:

- 1. When stored in original unopened containers at temperatures between 60° F (15.6°C) and 80° F (26.7 C), a shelf life of 12 months can be expected.
- 2. The expected shelf life can be shortened if product is stored in temperatures exceeding recommended storage levels.

RECOMMENDED STORAGE:

- 1. Store in original unopened containers at temperatures between 60° F and 80° F.
- 2. When stored in cooler temperatures, allow material to warm to room temperature before using.
- 3. Do not allow material to be stored in direct sunlight.
- 4. Rotate stock. Do not use product past 12 month shelf life.





See UL Roofing Materials and Systems Directory R10073

Information stated on this Roofing Products International, Inc. Data Sheet is intended to provide basic guidance as to storage, application, coverage, shipping, and other product data. Information is subject to change without notice. For more information regarding this product, refer to RPI MSDS, and the RPI Specification Manual. As neither Roofing Products International, Inc. nor its representatives practice structural engineering or architecture, RPI disclaims any responsibility and offers no opinion as to the structural soundness of any structure on which its products may be applied. The building owner should obtain the services of a competent structural engineer before proceeding. RPI accepts no responsibility for any structural failure or resultant damages. No Roofing Products International, Inc. representative is authorized to vary this disclaimer.



Roofing Products International, Inc.

57460 Dewitt St. Elkhart, IN 46517 Sales/Technical 1-800-628-2957 Fax: 574-294-3450 www.rpiroyaledge.com